

Tree Survey Report

Client: Ivybridge Town Council
 Site: Holman way



Ref.	What 3 Words	Species	Description	Measurements	Survey Notes	Str. Condition	Phys. Condition	Target Range	Size	PoF	RoH	Inspect Period	Recommendations	Photo
G001	///pocketed. otters. watching	Common holly x4 (<i>Ilex aquifolium</i>) Sycamore x2 (<i>Acer pseudoplatanus</i>) Common hawthorn x3 (<i>Crataegus monogyna</i>) Pedunculate oak (<i>Quercus robur</i>)	Target # - footpath Target # - road	Height (m): 9 Crown Radius (m): 5 Diameter (mm): 400 Trees: 10 Life Stage: Early Mature Life Exp.: 20+ Years	Vitality fair - mature oak tree to the north east is in neighbouring garden making the base of the tree difficult to assess (tree assessed from afar) Southern boundary has 4 dead trees. Risk assessment based on dead tree failure.	Fair	Fair	Human(4) 1/hour - 3/day	Size(3) 250mm - 110mm dia.	PoF(2) 1/10 - 1/100	1/500K	2 Years	Fell dead trees in southern boundary to prevent failure onto footpath Timescale: 06-Jun-2025 (1 Year)	